






Sample of Asset Inventory

Home ▶ Portfolio ▶ USA Division ▶ West Region ▶ California ▶ Gateway Building

Edit	ID	Asset Type	Description	Condition	Asset Status	Files	Priority	Length	Quantity	Current Life Cycle	Remaining Life	Standard Replacement Cost
Edit	16232	1511 - REPL PROPERTY NATURAL GAS DISTR.	Utility Dist Piping	1. Poor	Asset Functioning		4. Default	125 FT	52	1	\$5,000.00	
Edit	16233						4. Default	40 FT	50	1	\$1,600.00	
Edit	16234						4. Default	75 FT	50	1	\$3,750.00	
Edit	16235						4. Default	3 EA	20	1	\$3,000.00	
Edit	16236						4. Default	2 EA	20	1	\$2,000.00	
Edit	16237						1. High	1 EA	20	16	\$3,000.00	
Edit	16238						1. High	1 EA	20	9	\$4,000.00	
Edit	16229	114M - REPL HVAC AIR HANDLER UNIT/SUPPLY FAN (FAN, MOTOR)	HVAC Air Handler 1		Asset Functioning		1. High	1 EA	40	19	\$10,000.00	

Details

Utility Dist Piping - General - Windows Internet Explorer
 http://app2.axisfm.com/team/asset/assetedit.page?asset=16232

General ID Dimensions Attributes Costs Life Cycle Files Notes Location Attributes TCO

Description

Description: Utility Dist Piping

Asset Type: 1511 - REPL PROPERTY NATURAL GAS DISTR. [Change...](#)

Condition:

Asset Status: Asset Functioning

Investment Goal: 0%

Status %: 0%

Asset Manager: 31628 - REPL DISTRIBUTION Manager [Change...](#)

Location ID: Home / Portfolio / USA Division / West Region / California / [Change...](#)

Uses Unique Cost:

Funding Responsibility: Maintenance [Change...](#)

Zero Impact:

[Delete](#) [Close](#)

Done Internet 100%